


ADF or DME required.

ALS-F-2


MISSED APPROACH: Climb to 1500 then climbing right turn to 3000 direct XUB VOR and hold.

NA

ATIS132.75	COLUMBUS APP CON134.0279.6	RICK TOWER120.05348.4	GND CON125.275275.8	CLNC DEL125.275275.8
------------	----------------------------	-----------------------	---------------------	----------------------



ALTERNATE MISSED APCH FIX COBBS DD :::: 253 I-DDV 7.2



CATEGORY	A	B	C	D
S-ILS 5R	RA 100/12	100	DA 836	
CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED				

