

ILS or LOC RWY 34R
DENVER INTL (DEN)

MISSED APPROACH: Climb to 5800 then climbing left turn to 10000 on heading 270° and on FQF VORTAC R-306 to HYGEN/FQF 37.9 DME/RADAR and hold.

MISSED APCH FIX

114.2 GLL
R-221
Chan 89

HYGEN
FQF 37.9
RADAR

126°

306°

116.3 FQF
Chan 110

R-306

LOCALIZER 111.1
I-OUF 4.2
Chan 48

IM
5478
CADKO
I-OUF 4.2
RADAR

MSA DEN 25 NM

9200

[illegible]

SW-1. 18 APR 2024 to 16 MAY 2024