

LOC/DME I-DLS	APP CRS	Rwy Idg	4451
109.35	238°	TDZE	243
Chan 30(Y)		Apt Elev	247

LDA/DME RWY 25

COLUMBIA GORGE RGNL/THE DALLES MUNI(DLS)

NA

When local altimeter setting not received, procedure NA.
Glide slope provided by standard glide slope equipment.

MISSED APPROACH: Climb to 1600 then climbing left turn to 7000 on heading 120° and LTJ VOR/DME R-165 to JIREN/LTJ 15 DME and hold, continue climb-in-hold to 7000.

ASOS 135.175	SEATTLE CENTER 119.65 257.6	UNICOM 123.0 (CTAF) 0
------------------------	---------------------------------------	---------------------------------

ELEV 247

TDZE 243

REIL Rwy 31 0

MIRL Rwy 7-25 and 13-31 0

1600

7000

LTJ R-165

JIREN

Use I-DLS DME when on the localizer course.

↑

hdg 120°

VECCU I-DLS 13

CITAV I-DLS 10.5

LIREY I-DLS 8

One Minute Holding Pattern

3800

4500

5300

238°

058°

238°

7.9 NM

2.5 NM

2.5 NM

GS 4.20°

TCH 43

CATEGORY	A	B	C	D
S-LDA/GS 25	1368-3	1125 (1200-3)	NA	

THE DALLES, OREGON

Amdt 1A 28APR16

COLUMBIA GORGE RGNL/THE DALLES MUNI(DLS)

45°37'N-121°10'W

LDA/DME RWY 25