

LOC I-MBS 108.7	APP CRS 053°	Rwy Idg TDZE Apt Elev 8002 666 668
---------------------------	------------------------	--

ILS or LOC RWY 5
MBS INTL (MBS)

DME required.		MALSR	MISSED APPROACH: Climb to 1100 then climbing left turn to 2400 on heading 010° and MBS VOR/DME R-016 to SEEKS/MBS 13.9 DME and hold.			
V A * RVR 1800 authorized with use of FD or AP or HUD to DA.		A5 </				

