



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

INSTRUMENT APPROACH PROCEDURE CHARTS

IFR TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES

Civil Airports and Selected Military Airports

ALL USERS: Airports that have Departure Procedures (DPs) designed specifically to assist pilots in avoiding obstacles during the climb to the minimum enroute altitude , and/or airports that have civil IFR take-off minimums other than standard, are listed below. Take-off Minimums and Departure Procedures apply to all runways unless otherwise specified. Altitudes, unless otherwise indicated, are minimum altitudes in MSL.

DPs specifically designed for obstacle avoidance are referred to as Obstacle Departure Procedures (ODPs) and are described below in text, or published separately as a graphic procedure. If the (Obstacle) DP is published as a graphic procedure, its name will be listed below, and it can be found in either this volume (civil), or a separate Departure Procedure volume (military), as appropriate. Users will recognize graphic obstacle DPs by the term "(OBSTACLE)" included in the procedure title; e.g., TETON TWO (OBSTACLE). If not assigned a SID or radar vector by ATC, an ODP may be flown without ATC clearance to ensure obstacle clearance.

Graphic DPs designed by ATC to standardize traffic flows, ensure aircraft separation and enhance capacity are referred to as "Standard Instrument Departures (SIDs)". SIDs also provide obstacle clearance and are published under the appropriate airport section. ATC clearance must be received prior to flying a SID.

CIVIL USERS NOTE: Title 14 Code of Federal Regulations Part 91 prescribes standard take-off rules and establishes take-off minimums for certain operators as follows: (1) Aircraft having two engines or less - one statute mile. (2) Aircraft having more than two engines - one-half statute mile. These standard minima apply in the absence of any different minima listed below.

MILITARY USERS NOTE: Civil (nonstandard) take-off minima are published below. For military take-off minima, refer to appropriate service directives.

NAME TAKE-OFF MINIMUMS

ADAK ISLAND, AK

ADAK

TAKE-OFF MINIMUMS: **Rwy 5**, std. w/ min. climb of 370' per NM to 4400, or 4400-3 for climb in visual conditions. **Rwy 18**, NA-obstacles. **Rwy 23**, std. w/min. climb of 622' per NM to 4600, or 4400-3 for climb in visual conditions. **Rwy 36**, NA-obstacles.

DEPARTURE PROCEDURE: **Rwy 5**, climb via 054° bearing from ADK NDB/DME to 4400, then climbing right turn to 6000 direct ADK NDB/DME. Continue climb in ADK NDB/DME holding pattern (hold, northeast, right turn, 234° inbound) to cross ADK NDB/DME at or above MEA for route of flight, or for climb in visual conditions: cross ADK NDB/DME at or above 4300 before proceeding on course. **Rwy 23**, climb to 4600 direct ADK NDB/DME and via 234° bearing from ADK NDB/DME then climbing left turn to 6000 direct ADK NDB/DME, continue climb in ADK NDB/DME holding pattern (hold, northeast, right turn 234° inbound) to cross ADK NDB/DME at or above MEA for route of flight, or for climb in visual conditions: cross ADK NDB/DME at or above 4300 before proceeding on course.

AKHIOK, AK

AKHIOK

TAKE-OFF MINIMUMS: **Rwy 22**, N/A-obstacles.
DEPARTURE PROCEDURE: **Rwy 4**, use JOGMO DEPARTURE.

NAME TAKE-OFF MINIMUMS

ALLAKAKET, AK

ALLAKAKET

DEPARTURE PROCEDURE: **Rwy 5**, climb via heading 052° to 1500 before turning left. **Rwy 23**, climb via heading 232° to 1300 before turning right.

ALLEN AAF, AK 07354

DELTA JUNCTION/FORT GREELY

DEPARTURE PROCEDURE: **Rwys 19, 25, 28** climbing right turn via heading 332° and BIG VORTAC R-287 to 3500, thence... **Rwys 1, 7, 10**, climbing left turn via heading 242° and BIG VORTAC R-287 to 3500, thence...

...for V444 westbound departures continue on course, all others turn right direct BIG VORTAC or DJN NDB and proceed via airway radials/bearings on course.

NOTE: **Rwy 1**, multiple trees and fence beginning 46' from DER, 326' right of centerline, up to 59' AGL/1284' MSL. **Rwy 7**, multiple trees, fence, and REILS beginning 32' from DER, left and right of centerline, up to 67' AGL/1329' MSL. **Rwy 10**, multiple trees, fence, and REILS beginning 41' from DER, left and right of centerline, up to 70' AGL/1331' MSL. **Rwy 19**, multiple trees and power poles beginning 415' from DER, left and right of centerline, up to 46' AGL/1337' MSL. **Rwy 25**, multiple trees and fence beginning 86' from DER, left and right of centerline, up to 45' AGL/1317' MSL. **Rwy 28**, multiple trees and REILS beginning 4' from DER, left and right of centerline, up to 47' AGL/1301' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

AMBLER, AK

AMBLER

DEPARTURE PROCEDURE: **Rwy 36**, turn right.**Rwy 18**, turn left, climb SE bound on 150° bearing from AMF NDB to 2000, then climb on course.**ANAKTUVUK, AK**

ANAKTUVUK PASS

TAKE-OFF MINIMUMS: **Rwy 1**, CAT A,B, 5000-2, CAT C,D 5000-3 or std. with a min. climb of 350' per NM to 4800 required. **Rwy 19**, not authorized.DEPARTURE PROCEDURE: **Rwy 1**, use AKUMY ONE RNAV DEPARTURE.**ANCHORAGE, AK**

TED STEVENS ANCHORAGE INTL

TAKE-OFF MINIMUMS: **Rwy 7L**, 3300-1, or std. with a minimum climb of 320' per NM to 3400'. **Rwy 7R**, 2800-1 or std. with a minimum climb of 290' per NM to 2900.DEPARTURE PROCEDURE: Departures 020° CW to 160°. **Rwys 7L, 7R**, climb straight ahead to 2000 or ANC VOR/DME 9 DME/BGQ R-152, whichever comes first, then turn right to heading 190° to intercept ENA R-025. Continue in a climb to 5000, prior to proceeding on course. **Rwy 14**, turn right to 200°, climb to 2000, intercept the ENA R-025, climb to 5000 prior to proceeding on course. **Rwys 25L, 25R, 32**, climb direct ANC VOR/DME. Cross ANC VOR/DME at or above 4000, continue on course. If required, climb in a holding pattern, (SW, right turns, 053° inbound). Departures 161° CW to 270°. **Rwys 7L, 7R, 14**, departure as above to 3000 prior to proceeding on course. **Rwys 25L, 25R, 32**, climb on course. Departures 271° CW to 019°.**Rwys 7L, 7R**, climb to 2000, or the ANC 11 DME, left turn, climb inbound on the BGQ R-145 to 3000, then climb on course. **Rwy 14**, turn right, climb on course. **Rwys 25L, 25R, 32**, climb on runway heading to 2000, then climb on course.

MERRILL FIELD

TAKE-OFF MINIMUMS: **Rwys 4,22**, NA. **Rwy 25**, 400-1. **Rwy 16**, 500-1.DEPARTURE PROCEDURE: **Rwy 34**, climb on runway heading to 500. **Rwy 7**, turn right after take-off, N bound (360°) through SE bound (170°) IFR departures, climb direct to Anchorage VORTAC/ Campbell Lake NDB to cross VORTAC/Campbell Lake NDB at or above MCA before proceeding on course.**ANIAK, AK**

ANIAK

DEPARTURE PROCEDURE: **Rwy 10**, climb runway heading to 1800 before turning on course. **Rwy 28**, climb runway heading to 1300 before turning on course.**ARCTIC VILLAGE, AK**

ARCTIC VILLAGE

DEPARTURE PROCEDURE: Use TUVVO DEPARTURE.

ATKA, AK

ATKA

TAKE-OFF MINIMUMS: **Rwy 15**, 500-2. **Rwy 33**, 600-2.DEPARTURE PROCEDURE: **Rwy 15**, use ATKA ONE DEPARTURE. **Rwy 33**, use EIVRS ONE DEPARTURE.**BETHEL, AK**

BETHEL

TAKE-OFF MINIMUMS: **Rwy 29**, 300-2.DEPARTURE PROCEDURE: **All runways**, climb on runway heading to 500 before turning.**BETTLES, AK**

BETTLES

TAKE-OFF MINIMUMS: **Rwy 1**, std. w/ min. climb of 400' per NM to 2500 or 3100-2½ for climb in visual conditions.DEPARTURE PROCEDURE: **Rwy 1**, climb heading 012° to 2500 then climbing left turn to 3600 direct BTT VOR/DME. Climb in BTT VOR/DME holding pattern (hold south, left turn, 338° inbound) to cross BTT VOR/DME at or above 3600 or as directed by ATC. For climb in visual conditions: cross Bettles VOR/DME at or above 3600 MSL before proceeding on course. **Rwy 19**, climb heading 192° to 1800 then climbing left turn to 3600 direct BTT VOR/DME. Climb in BTT VOR/DME holding pattern (hold south, left turn, 338° inbound) to cross BTT VOR/DME at or above 3600 or as directed by ATC.NOTE: **Rwy 1**, multiple trees beginning 450' from departure end of runway, 267' right of centerline, up to 47' AGL/691' MSL. Multiple trees beginning 80' from departure end of runway, 148' left of centerline, up to 16' AGL/664' MSL. Antenna on building 395' from departure end of runway, 161' right of centerline, 14' AGL/658' MSL, DME antenna 412' from departure end of runway, 205' right of centerline, 12' AGL/656' MSL. **Rwy 19**, multiple trees beginning 140' from departure end of runway, 94' right of centerline up to 38' AGL/670' MSL. Multiple trees beginning 286' from departure end of runway, 152' left of centerline, up to 26' AGL/658' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008





TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

BIG LAKE, AK**BIG LAKE**

TAKE-OFF MINIMUMS: **Rwy 7**, 300-1 w/ a min. climb of 310' per NM to 700, or 900-2½ for climb in visual conditions. **Rwy 25**, 400-2 or std. w/ a min climb of 300' per NM to 700.

DEPARTURE PROCEDURE: **Rwy 7**, climbing left turn direct to BGQ VORTAC, thence..., or for climb in visual conditions: cross Big Lake Airport at or above 900 then proceed direct BGQ VORTAC, thence... **Rwy 25**, climbing right turn direct to BGQ VORTAC, thence... climb in holding pattern (hold south, left turn, 350° inbound) to MCA or MEA for route of flight.

NOTE: **Rwy 7**, bushes beginning 33' from departure end of runway, 335' left of centerline, up to 10' AGL/259' MSL. Multiple trees beginning 1150' from departure end of runway, 310' left of centerline, up to 85' AGL/434' MSL. Multiple trees beginning 2412' from departure end of runway, 594' right of centerline, up to 85' AGL/302' MSL. Terrain beginning 1.7 NM from departure end of runway, 470' right of centerline, 549' MSL. **Rwy 25**, multiple trees beginning 33' from departure end of runway, 129' left of centerline, up to 85' AGL/495' MSL. Multiple trees beginning 960' from departure end of runway, 185' right of centerline, up to 85' AGL/281' MSL. Terrain beginning 1.7 NM from departure end of runway, 1422' left of centerline, 511' MSL.

BUCKLAND, AK**BUCKLAND**

TAKE-OFF MINIMUMS: **Rwy 11**, std. w/ min. climb of 325' per NM to 1800, or 1900-3 for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 11**, climbing left turn to 3000 heading 280°, 314° bearing from BVK NDB and OTZR-133 to OTZ VOR/DME, before proceeding on course, or for climb in visual conditions: cross Buckland Airport at or above 1800 MSL before proceeding on course. **Rwy 29**, climbing right turn to 3000 via BVK 314° bearing and OTZR-133 to OTZ VOR/DME, before proceeding on course.

NOTE: **Rwy 11**, tower 1494' from departure end of runway, 112' right of centerline, 45' AGL/120' MSL. Trees 800' from departure end of runway, left and right of centerline, 50' AGL/99' MSL, tree 6001' from departure end of runway, 1169' left of centerline, 50' AGL/199' MSL.

CAPE LISBURNE LRRS, AK**CAPE LISBURNE**

TAKE-OFF MINIMUMS: **Rwy 8**, std with a min climb of 240' per NM to 500. Diverse departures NA.

DEPARTURE PROCEDURE: **Rwy 8**, use appropriate departure procedure. **Rwy 26**, NA.

NOTE: **Rwy 8**, rising terrain to 645' MSL, from DER out to 1.4 NM, from 197' to 992' right of centerline increasing to SE. Buildings and barge area to 80' MSL, 8' inward of DER, 56' to 84' left of centerline and 486' right of centerline. Buildings to 174' MSL, 2593' beyond DER, from 129' to 625' right of centerline.

CAPE NEWENHAM LRRS, AK**CAPE NEWENHAM**

DEPARTURE PROCEDURE: **Rwy 14**, NA. **Rwy 32**, use appropriate departure procedure.

NOTE: Diverse departures NA.

CAPE ROMANZOF LRRS, AK**CAPE ROMANZOF**

DEPARTURE PROCEDURE: **Rwy 2**, NA. **Rwy 20**, use appropriate departure procedure.

NOTE: Diverse departures NA.

CHEVAK, AK**CHEVAK**

NOTE: **Rwy 2**, vegetation beginning 76' from departure end of runway, 210' left of centerline, up to 15' AGL/89' MSL. **Rwy 20**, vegetation beginning 71' from departure end of runway, 231' left of centerline, up to 15' AGL/89' MSL.

COLD BAY, AK**COLD BAY**

TAKE-OFF MINIMUMS: **Rwys 26**, 800-2 1/2.

DEPARTURE PROCEDURE: **Rwy 8**, turn left.

Rwy 14, climb runway heading to 400 feet, then climbing left turn direct CDB VORTAC/CD LOM.

Rwy 26, immediate right climbing turn. **Rwy 32**, climb direct to CBD VORTAC/CD LOM. SW through NE bound (236° CW 025°) climb on course, NE through SW bound (026° CW 235°) climb to 5500 on 321° rad/ bearing of CDB VORTAC/CD LOM thence via assigned route.

COLDFOOT, AK**COLDFOOT**

DEPARTURE PROCEDURE: **Rwy 19**, Use BETTLES DEPARTURE.

CORDOVA, AK**MERLE K. (MUDHOLE) SMITH**

TAKE-OFF MINIMUMS: **Rwy 16**, NA- ATC. **Rwy 27**, std., do not exceed 210 knots until established on 200° bearing from GCR NDB. **Rwy 34**, NA- obstacles and ATC.

NOTE: **Rwy 9**, DME required.

NOTE: **Rwy 27**, ADF required.

DEPARTURE PROCEDURE: **Rwy 9**, climb to assigned altitude east on I-CDV course to FORAT/I-CDV 44.6 DME before proceeding on course. **Rwy 27**, climbing left turn via 200° bearing from GCR NDB to EYAKS Int, thence...

...climb in EYAKS Int holding pattern (S, RT, 020° inbound) to 5000 before proceeding on course.

NOTE: **Rwy 9**, multiple trees and bushes beginning 149' from departure end of runway, 150' right of centerline, up to 27' AGL/119' MSL. Multiple trees, bushes, and poles beginning 197' from departure end of runway, 106' left of centerline, up to 27' AGL/130' MSL. **Rwy 27**, multiple poles and bushes beginning 162' from departure end of runway, 261' right of centerline, up to 27' AGL/53' MSL. Multiple trees beginning 69' from departure end of runway, 431' left of centerline, up to 27' AGL/48' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

DEERING, AK

DEERING

TAKE-OFF MINIMUMS: **Rwy 11**, std. with a min. climb of 380' per NM to 1300, or 1000-2 ½ for climb in visual conditions. **Rwy 20**, 500-2 or std. with a min. climb of 320' per NM to 600. **Rwy 29**, 200-2½ or std. with a min. climb of 270' per NM to 300.

DEPARTURE PROCEDURE: **Rwy 11**, for climb in visual conditions: cross Deering Airport at or above 900.

NOTE: **Rwy 2**, tree 977' from departure end of runway, 555' left of centerline, 30' AGL/55' MSL. Multiple trees beginning 80' from departure end of runway, 10' right of centerline, up to 30' AGL/55' MSL. **Rwy 11**, tree 1.8 NM from departure end of runway, 9406' right of centerline, 30' AGL/511' MSL. Tree 1.7 NM from departure end of runway, 3171' right of centerline, 30' AGL/429' MSL. Tree 1.0' from departure end of runway, 552' left of centerline, 30' AGL/279' MSL. Tree 263' from departure end of runway, 235' right of centerline, 30' AGL/55' MSL. Tree 208' from departure end of runway, 157' left of centerline, 30' AGL/55' MSL. **Rwy 20**, tree 1.7 NM from departure end of runway, 7323' left of centerline, 30' AGL/511' MSL, tree 398' from departure end of runway, 318' left of centerline, 30' AGL/79' MSL. Multiple trees beginning 164' from departure end of runway, 63' right of centerline, up to 30' AGL/79' MSL. **Rwy 29**, tree 4779' from departure end of runway, 481' left of centerline, 30' AGL/179' MSL. Tree, 1.2 NM from departure end of runway, 892' right of centerline, 30' AGL/213' MSL, tree 3718' from departure end of runway, 1185' right of centerline, 30' AGL/154' MSL. Tree 942' from departure end of runway, 285' left of centerline, 30' AGL/104' MSL, tree 727' from departure end of runway, 254' right of centerline, 30' AGL/104' MSL.

DILLINGHAM, AK

DILLINGHAM

DEPARTURE PROCEDURE: **Rwy 1**, climb straight ahead to 500, northwestbound (270° CW 360°) turn right direct DLG VOR/DME. **Rwy 19**, northwestbound (270° CW 360°) climb straight ahead to DLG VOR/DME, then on course.

EIELSON AFB

FAIRBANKS, AK 07242

DEPARTURE PROCEDURE: Comply with assigned SID, or: **Rwy 32**, standard with Climb Gradient of 250 ft/ NM to 3800. **Rwy 14**, standard with Climb Gradient of 280 ft/NM to 3500.

VCOA DEPARTURE: Climb in Visual Conditions (Minimum Ceiling 2000', Minimum Visibility 3.00 SM) within 6.66 NM of PAEI airport, cross PAEI airport at or above 2400' MSL before proceeding on course. Max Airspeed 250 KIAS.

NOTE: **Rwy 32**, 85' AGL trees 2700' from departure end of runway, 1200' right of centerline. 70' AGL trees 3300' from departure end of runway, 1000' left of centerline. 85' AGL trees 1600' from departure end of runway, 850' left of centerline.

ELMENDORF AFB, AK

ANCHORAGE

TAKE-OFF MINIMUMS: **Rwy 16**, NA. **Rwy 34**, 400-1½ or std. with a min. climb of 360' per NM to 600.

DEPARTURE PROCEDURE: **Rwy 6**, turn left heading 290°. After completion of turn and passing 2200' proceed on course south through north bound (169° CW 005°). Climb on course maintain FL200 or ATC assigned altitude. North through southbound (005° CW 169°) departure not authorized. **Rwy 24**, south through north bound (169° CW 005°). Climb on course maintain FL200 or ATC assigned altitude. North through south bound (005° CW 169°) departure not authorized. **Rwy 34**, cross departure end of runway at or above 35' AGL/247' MSL. Climb at 360' per NM to 600. South through north bound (169° CW 005°). Climb on course maintain FL200 or ATC assigned altitude. North through south bound (005° CW 169°) departure not authorized.

NOTE: **Rwy 24**, 210' terrain 960' from departure end of runway 730' right of centerline, and 281' (21' AGL) trees 4100' from departure end of runway. **Rwy 34**, numerous trees to 444' MSL within 7300' of departure end of runway and 1850' left and right of centerline.

EMMONAK, AK

EMMONAK

NOTE: **Rwy 34**, bush 11' from departure end of runway, 146' left of centerline, 5' AGL/17' MSL.

FAIRBANKS, AK

FAIRBANKS INTL

DEPARTURE PROCEDURE: West and North bound (190° CW 020°), **Rwy 1L/R**, turn right, climb on 020° heading to 2000, **Rwy 19L/R**, climb runway heading to 2000, thence climb via assigned route.

FORT YUKON, AK

FORT YUKON

NOTE: **Rwy 4**, multiple trees beginning 500' from departure end of runway, 130' right of centerline, up to 30' AGL/479' MSL. **Rwy 22**, multiple trees beginning at departure end of runway, 204' left of centerline, up to 30' AGL/501' MSL, vehicle on road at departure end of runway, 188' left of centerline, 15' AGL/464' MSL.

GAMBELL, AK

DEPARTURE PROCEDURE: **Rwy 16,34**, climb on runway heading to 1000 before proceeding on course.

GOLOVIN, AK

GOLOVIN

DEPARTURE PROCEDURE: Use NOME DEPARTURE.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

GULKANA, AK

GULKANA

DEPARTURE PROCEDURE: **Rwy 15**, climb via heading 148° to 2800, then climbing left turn direct GKN VOR/DME or GLA NDB, thence. . . . **Rwy 33**, climb via heading 328° to 2800, then climbing left turn direct GKN VOR/DME or GLA NDB, thence. . . .

. . . . climb in holding pattern (GKN VOR/DME hold NW, right turn, 143° inbound), (GLA NDB hold NW, right turn, 143° inbound) to cross GKN VOR/DME at or above 4000 or GLA NDB at or above 10000.

NOTE: **Rwy 15**, multiple trees beginning 1175' from departure end of runway, 709' right of centerline, up to 40' AGL/1599' MSL. Multiple trees beginning 1194' from departure end of runway, 668' left of centerline up to 40' AGL/1599' MSL. **Rwy 33**, multiple trees and vehicles beginning 478' from departure end of runway, 514' left of centerline up to 40' AGL/1639' MSL. Multiple trees beginning 746' from departure end of runway, 631' right of centerline up to 40' AGL/1639' MSL.

GUSTAVUS, AK

GUSTAVUS

TAKE-OFF MINIMUMS: **Rwy 2**, 1500-2½ for climb in visual conditions. **Rwy 11**, std. with a min. climb of 260' per NM to 1200 or 1500-2½ for climb in visual conditions. **Rwy 20**, std. with a min. climb of 290' per NM to 1400 or 1500-2½ for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 2**, climb in visual conditions to cross departure end of Runway 11 eastbound at or above 1500, then climb to 5500 via SSR VORTAC R-288 (287° bearing from EEF NDB) to SSR VORTAC/EEF NDB. **Rwy 11**, climb via SSR VORTAC R-288 to SSR VORTAC, or via 287° bearing from EEF NDB to EEF NDB, or climb in visual conditions to cross departure end of Runway 11 eastbound at or above 1500, then climb to 5500 via SSR VORTAC R-288 (287° bearing from EEF NDB) to SSR VORTAC/EEF NDB.

Rwy 20, left turn via 155° heading and SSR VORTAC R-280 (282° bearing from EEF NDB) inbound to SSR VORTAC/EEF NDB, or climb in visual conditions to cross departure end of Runway 11 eastbound at or above 1500, then climb to 5500 via SSR VORTAC R-288 (287° bearing from EEF NDB) to SSR VORTAC/EEF NDB.

Rwy 29, left turn via 195° heading and SSR VORTAC R-280 (282° bearing from EEF NDB) inbound to SSR VORTAC/EEF NDB. All aircraft maintain 5500.

HOLY CROSS, AK

HOLY CROSS

DEPARTURE PROCEDURE: **Rwy 1**, climb via heading 013° to 900 before proceeding on course. **Rwy 19**, climb via heading 193° to 1000 before proceeding on course.

NOTE: **Rwy 1**, multiple trees beginning 11' from departure end of runway, 163' right of centerline, up to 60' AGL/159' MSL. Multiple trees beginning 14' from departure end of runway, 140' left of centerline, up to 60' AGL/159' MSL. **Rwy 19**, multiple trees beginning 21' from departure end of runway, 98' right of centerline, up to 60' AGL/159' MSL. Multiple trees beginning 48' from departure end of runway, 117' left of centerline, up to 60' AGL/159' MSL.

HOMER, AK

HOMER

DEPARTURE PROCEDURE: **Rwy 3**, climbing right turn to heading 240° to intercept and track out-bound on HOM R-200 or 210° bearing from ACE NDB.

Rwy 21, climb runway heading to intercept HOM R-200 or 210° bearing from ACE NDB. Northwest bound through Northeast bound (321° CW 030°), climb to 2500 via HOM R-200 or 210° bearing from ACE NDB, then direct HOM VOR/DME or ACE NDB. Cross HOM VOR/DME or ACE NDB at or above 4000, then climb on course. Northeast bound through Southeast bound (031° CW 150°), climb to 2500 via HOM R-200 or 210° bearing from ACE NDB, then direct HOM VOR/DME or ACE NDB. Cross HOM VOR/DME or ACE NDB at or above 5000, then climb on course. Southeast bound through Southwest bound (151° CW 199°), climb to 3400 via HOM R-200 or 210° bearing from ACE NDB then climb on course. Southwest bound through Northwest bound (200° CW 320°), climb to 2500 via HOM R-200 or 210° bearing from ACE NDB, then climb on course or comply with published Homer, Alaska SID.

HOOPER BAY, AK

HOOPER BAY

DEPARTURE PROCEDURE: **Rwy 31**, climb heading 316° to 800 before turning east.

NOTE: **Rwy 13**, mobile crane 527' from departure end of runway, 144' right of centerline, 80' AGL/107' MSL, pole 453' from departure end of runway, 446' left of centerline, 6' AGL/33' MSL, road 349' from departure end of runway, on centerline, 15' AGL/28' MSL, light on wind indicator 590' from departure end of runway, 389' left of centerline, 7' AGL/34' MSL, hanger 132' from departure end of runway, 361' left of centerline, 12' AGL/19' MSL.

ILIAMNA, AK

ILIAMNA

TAKE-OFF MINIMUMS: **Rwy 35**, 2400-2 or std. with min. climb to 400' per NM to 2700.

DEPARTURE PROCEDURE: **Rwy 35**, turn left as soon as practicable. **Rwy 25**, turn left. **Rwy 7**, turn right. SE clockwise to SW bound (110°-235°) climb on course. SW clockwise to SE bound (235°-110°) intercept the 180° bearing from ILI NDB/DME to 2000, then continue climb direct ILI NDB/DME. Climb as necessary in ILI NDB/DME std. holding pattern, 360° inbound, to depart ILI NDB/DME N to E bound (360°-110°) at or above 6000, R-99 E bound and SW to N bound (235°-360°) at or above 3000.

INDIAN MOUNTAIN LRRS, AK

UTOPIA CREEK

TAKE-OFF MINIMUMS: **Rwy 6**, 1500-2 or std. with a min. climb of 460' per NM to 1600. Diverse departures NA.

DEPARTURE PROCEDURE: **Rwy 6**, use appropriate departure procedure. **Rwy 24**, NA.

JUNEAU, AK

JUNEAU INTL

DEPARTURE PROCEDURE: **Rwys 8, 26**, Use CINGA DEPARTURE.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

KAKE, AK**KAKE**

TAKE-OFF MINIMUMS: **Rwy 28**, 500-2 or std. with a min. climb of 300' per NM to 500. **Rwy 10**, NA.

DEPARTURE PROCEDURE: **Rwy 28**, climb runway heading to 1000, then climbing left turn to 5000 direct AFE NDB and SQM NDB bearing 110° to SQM NDB, before proceeding on course.

KALSKAG, AK**KALSKAG**

TAKE-OFF MINIMUMS: **Rwy 6**, NA-high terrain.

DEPARTURE PROCEDURE: **Rwy 24**, climb via heading 243° to 1000 before proceeding on course.

NOTES: **Rwy 24**, numerous trees beginning 1000' from departure end of runway, on centerline, up to 100' AGL/154' MSL. Numerous trees beginning 750' from departure end of runway, 500' right of centerline, up to 100' AGL/154' MSL. Numerous trees beginning 960' left of centerline, up to 100' AGL/154' MSL.

KALTAG, AK**KALTAG**

TAKE-OFF MINIMUMS: **Rwy 3**, std. w/ a min. climb of 460' per NM to 4000, or 1300-3 for climb in visual conditions. **Rwy 21**, std. w/ a min. climb of 481' per NM to 4000, or 1300-3 for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 3**, climb via 029° heading to 1100 before proceeding on course or climb in visual conditions to cross Kaltag Airport at or above 2700 before proceeding on course. **Rwy 21**, climb via 209° heading to 1100 before proceeding on course or climb in visual conditions to cross Kaltag Airport at or above 2700 before proceeding on course.

TAKE-OFF NOTE: **Rwy 3**, trees 400' from departure end of runway, 400' right of centerline, 50' AGL/250' MSL.

KENAI, AK**KENAI MUNI**

DEPARTURE PROCEDURE: **Rwys 1L/R**, climb on a heading between 300° clockwise to 190° from departure end of runway. **Rwys 19L/R**, climb heading 192° to 1100, then climb on a heading between 222° counter clockwise to 010° from departure end of runway.

NOTE: **Rwy 1L**, multiple trees beginning 58' from departure end of runway, 349' right of centerline, up to 60' AGL/113' MSL. Multiple trees beginning 67' from departure end of runway, 376' left of centerline, up to 60' AGL/121' MSL. **Rwy 1R**, tree 1034' from departure end of runway, 264' right of centerline, 60' AGL/134' MSL. Multiple trees beginning 314' from departure end of runway, 477' left of centerline, up to 60' AGL/108' MSL. **Rwy 19L**, multiple buildings and antennas beginning 2053' from departure end of runway, 662' left of centerline, up to 63' AGL/169' MSL. **Rwy 19R**, multiple bushes and trees 24' from departure end of runway, 90' right of centerline, up to 60' AGL/148' MSL. Multiple trees beginning 986' from departure end of runway, 160' left of centerline, up to 60' AGL/147' MSL. Pole 492' from departure end of runway, 600' left of centerline, 33' AGL/125' MSL.

KETCHIKAN, AK**KETCHIKAN INTL**

TAKE-OFF MINIMUMS: **Rwy 11**, 3000-2 or std. with min. climb of 340' per NM to 3400. **Rwy 29**, 1000-2 or std. with min. climb of 380' per NM to 1000.

DEPARTURE PROCEDURE: **Rwy 11**, climb at 340' per NM to 3400 on 109° bearing from CMJ NDB to intercept ANN R-326 to ANN VOR/DME or 150° bearing to ICK NDB. West and north westbound turn right heading 250° passing 3500 inbound to ANN VOR/DME or ICK NDB and continue climb to intercept assigned route. Southeastbound climb to cross ANN VOR/DME or ICK NDB at or above 4500. **Rwy 29**, climb at 380' per NM to 1000. North westbound on V317, A15, and J502 climb on I-ECH LOC west course to intercept airways. Cross I-ECH 20 DME at or above 4100, continue climb on course. All other departures climb on I-ECH LOC west course to I-ECH 10 DME, then turn left heading 230°. Passing 4500 continue climb on course.

KIANA, AK**BOB BAKER MEMORIAL**

DEPARTURE PROCEDURE: **Rwy 6**, Use SELAWIK DEPARTURE.

KING COVE, AK**KING COVE**

DEPARTURE PROCEDURE: **Rwy 7**, Use Cold Bay RNAV departure.

KING SALMON, AK**KING SALMON**

NOTE: **Rwy 11**, multiple bushes and trees beginning 188' from departure end of runway, 330' left of centerline, up to 30' AGL/108' MSL. **Rwy 36**, multiple trees beginning 750' from departure end of runway, 8' left of centerline, up to 30' AGL/93' MSL. Bush and tree beginning 59' from departure end of runway, 180' right of centerline, 30' AGL/87' MSL. Road and vehicle, 721' from departure end of runway, up to 15' AGL/81' MSL.

KLAWOCK, AK**KLAWOCK**

TAKE-OFF MINIMUMS: **Rwy 2**, NA. **Rwy 20**, 1000-3 or std. with a min. climb of 390' per NM to 2500.

DEPARTURE PROCEDURE: **Rwy 2**, NA. **Rwy 20**, climb to 2500 via 207° bearing from AKW NDB/DME, then climbing right turn to 6000 direct AKW NDB/DME and 015° bearing from AKW NDB/DME to UDENE/ANN 59 DME before proceeding on course.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

KOBUK, AK

KOBUK (OBU)

ORIG 07354 (FAA)

TAKE-OFF MINIMUMS: **Rwy 27**, 300-1 or std. w/ a min. climb of 661' per NM to 400.DEPARTURE PROCEDURE: **Rwy 9**, climbing right turn via heading 220° and AMF NDB 283° course to AMF NDB before proceeding on course. **Rwy 27**, climb via heading 267° and AMF NDB 283° course to AMF NDB before proceeding on course.NOTE: **Rwy 9**, multiple trees beginning 169' from departure end of runway, 36' right of centerline, up to 50' AGL/199' MSL. Multiple trees beginning 231' from departure end of runway, 385' left of centerline, up to 50' AGL/199' MSL. **Rwy 27**, multiple trees beginning 79' from departure end of runway, 220' left of centerline, up to 50' AGL/182' MSL. Multiple trees beginning 17' from departure end of runway, 299' right of centerline, up to 50' AGL/249' MSL.**KODIAK, AK**

KODIAK

TAKE-OFF MINIMUMS: **Rwy 25**, NA-terrain.DEPARTURE PROCEDURE: **Rwys 7, 11, 18, 29, 36**,

Use KODIAK DEPARTURE.

KOKHANOK, AK

KOKHANOK

TAKE-OFF MINIMUMS: **Rwy 6**, 400-1½ or std. w/ min. climb of 420' per NM to 600.DEPARTURE PROCEDURE: **Rwy 6**, climbing left turn direct ILI NDB/DME, climb in ILI NDB/DME holding pattern (South, right turn, 360° inbound) to cross ILI NDB/DME at or above MEA for route of flight. **Rwy 24**, climbing right turn direct ILI NDB/DME, climb in ILI NDB/DME holding pattern (South, right turn, 360° inbound) to cross ILI NDB/DME at or above MEA for route of flight.NOTE: **Rwy 6**, multiple trees beginning 58' from departure end of runway, 40' left of centerline, up to 60' AGL/309' MSL. Multiple trees beginning 240' from departure end of runway, 86' right of runway centerline, up to 60' AGL/459' MSL. **Rwy 24**, multiple trees beginning 3356' from departure end of runway, 914' left of centerline, up to 60' AGL/209' MSL. Multiple trees beginning 3723' from departure end of runway, 689' right of centerline, up to 60' AGL/209' MSL.**KOLIGANEK, AK**

KOLIGANEK

TAKE-OFF MINIMUMS: **Rwy 9**, 300-2 or std. with a min. climb of 205' per NM to 700'. Alternatively, with standard takeoff minimums and a normal 200'/NM climb gradient, takeoff must occur no later than 1300' prior to departure end of runway.DEPARTURE PROCEDURE: **Rwy 9**, climb via heading 087° to 1200 before proceeding on course. **Rwy 27**, climb via heading 267° to 1500 before proceeding on course.NOTE: **Rwy 9**, multiple trees beginning 133' from departure end of runway, 238' right of centerline, up to 50' AGL/399' MSL. Multiple trees beginning 262' from departure end of runway, 194' left of centerline, up to 50' AGL/389' MSL. AAO 1.65 NM from departure end of runway, on centerline, 200' AGL/524' MSL. **Rwy 27**, multiple bushes beginning 75' from departure end of runway, 145' left of centerline, up to 25' AGL/299' MSL. Multiple trees beginning 242' from departure end of runway, 147' right of centerline up to 50' AGL/309' MSL. Powerlines 1986' from departure end of runway, right and left of centerline, 50' AGL/309' MSL.**KOTZEBUE, AK**

RALPH WIEN MEMORIAL

TAKE-OFF MINIMUMS: **Rwy 18**, 300-1¼ or std. w/ min. climb of 280' per NM to 300.NOTE: **Rwy 9**, multiple bushes beginning 735' from departure end of runway, 265' right of centerline, up to 15' AGL/136' MSL. Multiple bushes beginning 1122' from departure end of runway, 2' left of centerline, up to 15' AGL/105' MSL. Car, tower and obstruction light VOR/DME beginning 4114' from departure end of runway, on centerline, up to 27' AGL/147' MSL. **Rwy 18**, vehicle on road, 12' from departure end of runway, on centerline, 15' AGL/25' MSL. Tower 5819' from departure end of runway, 1690' left of centerline, 100' AGL/218' MSL. **Rwy 27**, vehicle on road, 79' from departure end of runway, on centerline, 15' AGL/25' MSL, sign 68' from departure end of runway, 367' right of centerline, 5' AGL/18' MSL. Sign 77' from departure end of runway, 248' left of centerline, 5' AGL/18' MSL. **Rwy 36**, multiple towers beginning 378' from departure end of runway, 533' left of centerline, up to 66' AGL/ 76' MSL. Rod on obstruction light AMOM 312' from departure end of runway, 299' right of centerline, 15' AGL/38' MSL. Vehicle on road, 11' from departure end of runway, on centerline, 15' AGL/24' MSL.**KOYUK, AK**

KOYUK ALFRED ADAMS

TAKE-OFF MINIMUMS: **Rwy 1**, (Days) 900-2 or std. with a min. climb of 360' per NM to 1100. **Rwy 1**, (Nights) std. with a min. climb of 360' per NM to 1100.DEPARTURE PROCEDURE: **Rwy 1**, climb via 015° bearing from KKA NDB/DME to 2000 before proceeding on course. **Rwy 19**, climb via 184° bearing from KKA NDB/DME to 2000 before proceeding on course.**KWIGILLINGOK, AK**

KWIGILLINGOK

NOTE: **Rwy 15**, trees 25' from departure end of runway, 325' right of centerline, 35' AGL/53' MSL. **Rwy 33**, trees 60' from departure end of runway, 80' right of centerline, 35' AGL/53' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

LADD AAF, AK

FAIRBANKS/FORT WAINWRIGHT 06215

DEPARTURE PROCEDURE: Rwy 24, turn left.
Rwy 6, climb straight ahead direct to CUN NDB.
West and northbound (190° thru 020°) climb in
CUN holding pattern (NE, left turns 241°
inbound), to 3200 before proceeding on course.

MANOKOTAK, AK

MANOKOTAK

TAKE-OFF MINIMUMS: **Rwys 1, 19**, 2500-2½ for climb
in visual conditions, NA at night.
DEPARTURE PROCEDURE: **Rwys 1, 19**, procedure NA
at night. Climb in visual conditions to cross Manokotak
Airport at or above 2400 before proceeding on course.
Do not exceed 210 knots until proceeding on course.
NOTE: **Rwy 1**, terrain beginning 3759' from departure end
of runway, 1076' right of centerline, up to 542' MSL.
Rwy 19, terrain 2597' from departure end of runway 1170'
left of centerline, 349' MSL.

MARSHALL, AK

MARSHALL DON HUNTER SR

TAKE-OFF MINIMUMS: **Rwy 7**, 1800-3 or std. with a
min. climb gradient of 470' per NM to 1800.
DEPARTURE PROCEDURE: **Rwys 7, 25**, use BIBNE
RNAV DEPARTURE.
NOTE: **Rwy 7**, trees 3500' right of departure end of
runway, 60' AGL/709' MSL. Trees 4500' right of
departure end of runway, 60' AGL/1059' MSL.

MCGRATH, AK

MCGRATH

TAKE-OFF MINIMUMS: **Rwy 8**, std. w/ min. climb of 425'
per NM to 2200, or 2300-3 for climb in visual conditions.
Rwy 16, std. w/ min. climb of 470' per NM to 1700, or
2300-3 for climb in visual conditions. **Rwy 26**, std. w/
min. climb of 435' per NM to 2200, or 2300-3 for climb in
visual conditions. **Rwy 34**, std. w/ min. climb of 420' per
NM to 2200, or 2300-3 for climb in visual conditions.
DEPARTURE PROCEDURE: **Rwy 8**, climb via heading
075° to 2200, then climbing right turn thence... or for
climb in visual conditions: cross McGrath Airport at or
above 2200, thence... **Rwy 16**, climb via heading 160° to
1700, then climbing left turn via heading 014° thence...
or for climb in visual conditions: cross McGrath Airport
at or above 2200, thence... **Rwy 26**, climb via heading
255° to 2200, then climbing right turn direct MCG
VORTAC or VTR NDB, thence... or for climb in visual
conditions: cross McGrath Airport at or above 2200,
thence... **Rwy 34**, climb via heading 340° to 2200, then
climbing right turn heading 166° to MCG R-104 or
direct VTR NDB thence... or for climb in visual
conditions: cross McGrath Airport at or above 2200,
thence...
...climb to 4000 southeast bound via MCG R-104, or 097°
bearing from VTR NDB. Aircraft southeast bound (079°
clockwise 119°) continue climb on course to MEA for
route of flight. All others reverse course via the MCG
R-104 to MCG VORTAC, or 277° course to VTR NDB,
then continue climb on course to MEA for route of flight.
NOTE: **Rwy 8**, tower 532' from departure end of runway,
368' right of centerline, up to 60' AGL/400' MSL. **Rwy
16**, trees beginning 2.2 NM from departure end of
runway, 2392' left of centerline, up to 80' AGL/1346'
MSL.

MEKORYUK, AK

MEKORYUK

DEPARTURE PROCEDURE: **Rwy 23**, climb heading
234° to 900 before turning left.
NOTE: **Rwy 5**, tree 1028' from departure end of runway,
745' left of centerline, 15' AGL/114' MSL, tree 1619' from
departure end of runway, 862' left of centerline, 15' AGL/
114' MSL, road 41' from departure end of runway, 302'
left of centerline, 15' AGL/50' MSL. **Rwy 23**, tree 75'
from departure end of runway, 200' left of centerline, 15'
AGL/64' MSL, tree 62' from departure end of runway, on
centerline, 15' AGL/64' MSL, tree 482' from departure
end of runway, 157' right of centerline, 15' AGL/114'
MSL.

MINCHUMINA, AK

MINCHUMINA

TAKE-OFF MINIMUMS: **Rwy 3**, 1600-3 for climb in
visual conditions. Procedure NA at night
DEPARTURE PROCEDURE: **Rwy 3**, for climb in visual
conditions: Cross MHM NDB north bound at or above
1600 MSL before proceeding on course. **Rwy 21**, climb
via heading 204° to 1600 before proceeding on course.
NOTE: **Rwy 3**, trees 269' from departure end of runway,
540' left of centerline, 45' AGL/749' MSL. Trees 170'
from departure end of runway, 340' left of centerline, 45'
AGL/964' MSL.

MOUNTAIN VILLAGE, AK

MOUNTAIN VILLAGE

NOTE: **Rwy 2**, bush 14' from departure end of runway,
208' left of centerline, 15' AGL/355' MSL.

NELSON LAGOON, AK

NELSON LAGOON

DEPARTURE PROCEDURE: Use BINAL
DEPARTURE.

NENANA, AK

NENANA MUNI

TAKE-OFF MINIMUMS: **Rwy 4L**, 1400-2 or std. with a
min. climb of 330' per NM to 1100. **Rwys 4R, 4W, 22L,
22W**, NA-ATC.
DEPARTURE PROCEDURE: **Rwy 4L**, climbing right
turn via heading 125° to 1900 then climbing right turn
direct ENN VORTAC, thence... **Rwy 22R**, climb via
heading 212° to 1800 then climbing left turn direct ENN
VORTAC, thence...
...continue climb in ENN VORTAC holding pattern (SW,
LT, 036° inbound) to MEA for route of flight before
proceeding on course.
NOTE: **Rwy 4L**, multiple trees beginning 2352' from
departure end of runway, 34' right of centerline, up to 60'
AGL/459' MSL. Multiple trees beginning 2448' from
departure end of runway, 759' left of centerline, up to 60'
AGL/459' MSL. Multiple trees beginning 1.82 NM from
departure end of runway, 2492' left of centerline up to 60'
AGL/859' MSL. **Rwy 22R**, multiple trees 1321' from
departure end of runway, 782' right of centerline, up to
60' AGL/459' MSL. Multiple trees beginning 1881' from
departure end of runway, 194' left of centerline, up to 60'
AGL/459' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

NEW STUYAHOK, AK

NEW STUYAHOK (KNW)

AMDT 1 07354 (FAA)

NOTE: **Rwy 14**, tree 700' from departure end of runway, 647' right of centerline, 60' AGL/409' MSL. Multiple trees beginning 549' from departure end of runway, 499' left of centerline, up to 60' AGL/434' MSL. **Rwy 32**, tree 743' from departure end of runway, 104' right of centerline, 60' AGL/445' MSL.

NIKOLAI, AK

NIKOLAI

DEPARTURE PROCEDURE: **Rwy 4**, climbing left turn to 6000 via heading 224° and MCG VORTAC R-055 to MCG VORTAC, thence...**Rwy 22**, climb to 6000 via heading 224° and MCG VORTAC R-065 to MCG VORTAC, thence...

...continue climb in MCG VORTAC holding pattern (hold east, right turn, 280° inbound) to cross MCG VORTAC at or above MEA/MCA for route of flight.

NOTE: **Rwy 4**, multiple trees beginning 145' from departure end of runway, 534' left of centerline, up to 50' AGL/549' MSL; multiple trees beginning 229' from departure end of runway, 531' right of centerline, 50' AGL/549' MSL. **Rwy 22**, multiple trees, power poles, and buildings beginning 48' from departure end of runway, 32' left of centerline, up to 50' AGL/549' MSL; multiple trees and power pole 365' from departure end of runway, 187' right of centerline, 30' AGL/471' MSL.

NOATAK, AK

NOATAK

DEPARTURE PROCEDURE: **Rwy 1**, climb via heading 007° to 1900 before proceeding on course.

NOTE: **Rwy 1**, multiple buildings and trees beginning 475' from departure end of runway, 221' right of centerline, up to 30' AGL/104' MSL. Tower 1938' from departure end of runway, 875' left of centerline, 47' AGL/146' MSL.

NOME, AK

NOME

TAKE-OFF MINIMUMS: **Rwy 3**, std. with a min. climb of 467' per NM to 1800, or 1300-3 for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 3**, climbing right turn direct NOME VOR/DME, thence...or climb in visual conditions to cross Nome Airport at or above 1200 before proceeding on course. **Rwy 10**, climb via heading 096° to 1200 thence...**Rwys 21, 28**, turn left direct NOME (OME) VOR/DME/FORT DAVIS (FDV) NDB, thence...departures northeast CW through west bound (040 CW 260), climb on course. Departures west through northeast bound (260 CW 040), climb south bound on OME R-138° or 145° bearing from FDV NDB to 2200 then turn right via direct NOME (OME) VOR/DME/FORT DAVIS (FDV) NDB. Continue climb on course.

NOTE: **Rwy 3**, bush 112' from departure end of runway, 250' left of centerline, 58' AGL/58' MSL. Bush 15' from departure end of runway, 315' right of centerline, 50' AGL/53' MSL. Bush 294' from departure end of runway, 445' right of centerline, 50' AGL/57' MSL. Pole 2116' from departure end of runway, 313' left of centerline, 90' AGL/100' MSL. Pole 1656' from departure end of runway 234' right of centerline, 78' AGL/88' MSL. Bush 147' from departure end of runway, 135' left of centerline, 40' AGL/49' MSL. Bush 81' from departure end of runway, 203' right of centerline, 40' AGL/47' MSL. Bush 283' from departure end of runway, 72' right of centerline, 40' AGL/48' MSL. Pole 2415' from departure end of runway, 495' left of centerline, 90' AGL/101' MSL. AAO 5.84 NM from departure end of runway, 3268' right of centerline, 200' AGL/1352' MSL. **Rwy 10**, pole 1754' from departure end of runway, 924' left of centerline, 83' AGL/93' MSL. Obstruction light on pole 1873' from departure end of runway, 612' left of centerline, 50' AGL/86' MSL. Obstruction light pole 419' from departure end of runway, 470' right of centerline, 28' AGL/48' MSL. Antenna on building 1075' from departure end of runway, 742' left of centerline, 33' AGL/63' MSL. Building 1101' from departure end of runway, 759' left of centerline, 27' AGL/63' MSL. Antenna on building 766' from departure end of runway, 588' right of centerline, 30' AGL/54' MSL. Truck on road 2' from departure end of runway, 500' right of centerline, 15' AGL/30' MSL. Obstruction light on pole 1729' from departure end of runway, 595' left of centerline, 50' AGL/71' MSL. Truck on road 209' from departure end of runway, 79' right of centerline, 15' AGL/30' MSL. Pole 1744' from departure end of runway, 569' left of centerline, 43' AGL/68' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008





TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

NOME (CON'T.)

Rwy 20, truck on road 549' from departure end of runway, 249' right of centerline, 35' AGL/50' MSL. Road 625' from departure end of runway, 12' left of centerline, 32' AGL/47' MSL. Bush 803' from departure end of runway, 412' left of centerline, 8' AGL/50' MSL. Pole 1549' from departure end of runway, 471' left of centerline, 52' AGL/62' MSL. Pole 1594' from departure end of runway, 506' left of centerline, 52' AGL/62' MSL. Pole 1621' from departure end of runway, 342' left of centerline, 52' AGL/62' MSL. Ground 839' from departure end of runway, 388' right of centerline, 0' AGL/40' MSL. Pole 1756' from departure end of runway 85' left of centerline, 52' AGL/62' MSL. Ground 945' from departure end of runway, 344' left of centerline, 0' AGL/37' MSL. **Rwy 28**, pole 101' from departure end of runway, 520' left of centerline, 36' AGL/72' MSL. Pole 129' from departure end of runway, 521' left of centerline, 62' AGL/72' MSL. Building 422' from departure end of runway, 528' left of centerline, 32' AGL/57' MSL. Ground 906' from departure end of runway, 436' left of centerline, 0' AGL/60' MSL. Ground 374' from departure end of runway, 476' left of centerline, 0' AGL/36' MSL. Antenna on building 1335' from departure end of runway, 203' left of centerline, 31' AGL/51' MSL.

NONDALTON, AK

NONDALTON

TAKE-OFF MINIMUMS: **Rwy 2**, NA-obstacles.
DEPARTURE PROCEDURE: **Rwy 20**, Use ILIAMNA DEPARTURE.

NORTHWAY, AK

NORTHWAY

DEPARTURE PROCEDURE: **Rwy 5**, climbing right turn to 4000 via ORT R-100, then climbing right turn to 8000 direct ORT VORTAC, continue climb in ORT VORTAC holding pattern (West, right turn, 108° inbound) to 8000 before proceeding on course. . . . **Rwy 23**, climbing left turn to 4000 via ORT R-170, then climbing left turn to 8000 direct ORT VORTAC, continue climb in ORT VORTAC holding pattern (West, right turn, 108° inbound) to 8000 before proceeding on course. . . .

. . . continue climb via assigned route.

NOTE: **Rwy 5**, multiple trees beginning 1133' from departure end of runway, 727' right of centerline, up to 60' AGL/1859' MSL. Multiple trees beginning 3881' from departure end of runway, 1522' left of centerline, up to 60' AGL/1859' MSL. **Rwy 23**, multiple trees beginning 777' from departure end of runway, 560' left of centerline, up to 60' AGL/1809' MSL. Multiple trees beginning 1365' from departure end of runway, 527' right of centerline, up to 60' AGL/1809' MSL.

NULATO, AK

NULATO

TAKE-OFF MINIMUMS: **Rwy 2**, 700-2½ with minimum climb of 356 feet per NM to 1300 or 1000-3 for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 2**, climb via heading 024° to 1300 before proceeding on course or climb in visual conditions to cross Nulato Airport at or above 1300 before proceeding on course. **Rwy 20**, climb via heading 204° to 1500 before proceeding on course.

NOTE: **Rwy 2**, tree 3078' from departure end of runway 355' left of centerline 100' AGL 655' MSL. Tree 5041' from departure end of runway 154' right of centerline 100' AGL 699' MSL. Tree 1.03 NM from departure end of runway 122' right of centerline 100' AGL 799' MSL. Tree 1.24 NM from departure end of runway 705' left of centerline 100' AGL 899' MSL. Tree 1.44 NM from departure end of runway 2385' left of centerline 100' AGL 999' MSL. Tree 2.57 NM from departure end of runway 5740' left of centerline 100' AGL 1035' MSL. **Rwy 20**, tree 3.33 NM from departure end of runway 1.64 NM right of centerline 100' AGL 957' MSL. Tree 3.10 NM from departure end of runway 1.94 NM right of centerline 100' AGL 965' MSL. Tree 1.49 NM from departure end of runway 7.39 NM right of centerline 200' AGL 1850' MSL.

PALMER, AK

PALMER MUNI

TAKE-OFF MINIMUMS: **Rwy 9**, NA. **Rwy 34**, 500-1½ or std. w/min. climb of 482' per NM to 800.

DEPARTURE PROCEDURE: Use PALMER RNAV DEPARTURE.

NOTE: **Rwy 27**, 100' AGL trees 1500' from departure end of runway, 200' right of centerline. Trees, 1500' from departure end of runway, 200' right of centerline, 48' AGL/200' MSL. **Rwy 34**, tree 5239' from departure end of runway, 1900' right of centerline, 60' AGL/659' MSL.

PERRYVILLE, AK

PERRYVILLE

TAKE-OFF MINIMUMS: **Rwy 2**, NA-obstacles.
DEPARTURE PROCEDURE: **Rwy 20**, Use CLAC (RNAV) DEPARTURE.

PETERSBURG, AK

PETERSBURG JAMES A. JOHNSON

TAKE-OFF MINIMUMS: **Rwys 4, 22**, turn left; climb VFR to 2000-3 or 1000-3 with a min. climb of 300' per NM to 5000. Night IFR, NA for **Rwy 22**.

DEPARTURE PROCEDURE: **Rwy 4** turn left, **Rwy 22**, turn right immediately; climb VFR to 2000 (1000 with 300/NM climb restriction) within 1.5 miles NW of airport; depart from over airport to intercept the I-PSG LDA NW course or fly heading of 010° to intercept the 320° bearing from FPN NDB. Climb to I-PSG 10 DME, then turn left, continue climb to 7000 on 280° heading. Transition: NW-bound departures intercept V-317, J-502, A-15, B-37. SE-bound departures proceed direct to LVD VOR or SQM NDB.

PILOT POINT, AK

PILOT POINT

DEPARTURE PROCEDURE: Use ZILKO RNAV DEPARTURE

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

PLATINUM, AK**PLATINUM**TAKE-OFF MINIMUMS: **Rwys 9,13**, NA.DEPARTURE PROCEDURE: **Rwys 27,31**, climb runway heading to 2200 before turning southbound.**POINT LAY LRRS, AK**

NOTE: Special Aircrew Certification Required.

NOT FOR CIVIL USE**PORT HEIDEN, AK****PORT HEIDEN**

DEPARTURE PROCEDURE: **Rwy 5**, climb heading 054° to 1000, then climbing left turn to 2500 direct PDN NDB/DME, thence... **Rwy 13**, climb heading 131° to 1000, then climbing right turn to 2500 direct PDN NDB/DME, thence... **Rwy 23**, climbing right turn to 2500 direct PDN NDB/DME, thence... **Rwy 31**, climbing left turn to 2500 direct PDN NDB/DME, thence...
 ...continue climb in PDN NDB/DME holding pattern (hold southwest, left turn, 052° inbound) to cross PDN NDB at or above MEA for route of flight.

RUBY, AK**RUBY**TAKE-OFF MINIMUMS: **Rwy 3**, std. from 355° bearing clockwise to 312° bearing, NA from 313° bearing to 354° bearing. **Rwy 21**, 700-2 or std. with 350° per NM climb to 1500.NOTE: **Rwy 21**, trees 4700 to 6700' from departure end of runway, 250' left of centerline to 1600' right of centerline, 50' AGL/854' MSL.**RUSSIAN MISSION, AK****RUSSIAN MISSION**TAKE-OFF MINIMUMS: **Rwy 17**, 500-2 with a min. climb of 405' per NM to 2900 or 1900-2 for climb in visual conditions. Climb in visual conditions NA at night. **Rwy 35**, 500-2 with a min. climb of 330' per NM to 3700 or 1900-2 for climb in visual conditions. Climb in visual conditions NA at night.DEPARTURE PROCEDURE: **Rwys 17, 35**, for climb in visual conditions: cross Russian Mission Airport at or above 1800. Do not exceed 180 knots until proceeding on course.NOTE: **Rwy 17**, multiple trees beginning 1232' from departure end of runway, 808' right of centerline, up to 80' AGL/1007' MSL. **Rwy 35**, trees 2380' from departure end of runway, 1036' left of centerline, 80' AGL/329' MSL.**ST. GEORGE, AK****ST. GEORGE**TAKE-OFF MINIMUMS: **Rwy 11**, 800-1 or std. with 320' per NM climb to 800'. **Rwy 29**, 600-1 or std. with 350' per NM climb to 800'.DEPARTURE PROCEDURE: **Rwy 11**, immediate right turn, climb to 1100' via 210° heading to intercept 180° bearing from SRI NDB/DME, then climb on course. **Rwy 29**, immediate left turn, climb to 1100' via 160° heading to intercept 180° bearing from SRI NDB/DME, then climb on course.**ST. MARYS, AK****ST. MARYS**TAKE-OFF MINIMUMS: **Rwys 6,17,24**, 200-1.DEPARTURE PROCEDURE: **Rwys 6,17,24,35**, climb straight ahead to 1000, continue climb on course.**ST. MICHAEL, AK****ST. MICHAEL**DEPARTURE PROCEDURE: **Rwy 20**, climb via heading 196° to 700' before turning right.NOTE: **Rwy 2**, tree 36' from departure end of runway, 377' right of centerline, 20' AGL/83' MSL. **Rwy 20**, terrain beginning 2' to 2276' from departure end of runway, 51' to 966' right of centerline, up to 151' MSL. Terrain beginning 110' to 917' from departure end of runway, 13' to 533' left of centerline, up to 119' MSL. Tree 1779' from departure end of runway, 504' right of centerline, 20' AGL/219' MSL. Tree 1.2 NM from departure end of runway 1 NM right of centerline, 20' AGL/520' MSL.**ST. PAUL ISLAND, AK****ST. PAUL ISLAND**DEPARTURE PROCEDURE: **Rwy 18**, climb via heading 180° and via 165° bearing from SPY NDB/DME to 2000 before proceeding on course. **Rwy 36**, climb via heading 360° and via 360° bearing from SPY NDB/DME to 2000 before proceeding on course.NOTE: **Rwy 18**, post 98' from departure end of runway, 421' left of centerline, 6' AGL/39' MSL. **Rwy 36**, rising terrain beginning 133' from departure end of runway, up to 79' MSL.**SAND POINT, AK****SAND POINT**TAKE-OFF MINIMUMS: **Rwy 13**, 600-1 or std. with min. climb of 360' per NM to 1000'. **Rwy 31**, 600-3 or std. with min. climb of 360' per NM to 1000'.DEPARTURE PROCEDURE: **Rwy 13**, climb via 134° bearing from HBT NDB/DME to 2200' then climbing left turn direct HBT NDB/DME, thence... **Rwy 31**, climb via 314° bearing from HBT NDB/DME to 1800', then climbing right turn direct HBT NDB/DME, thence...
 ...climb in HBT NDB/DME holding pattern (southeast, right turn, 340° inbound) to 10,000' before proceeding on course.NOTE: **Rwy 13**, cliff beginning 244' from departure end of runway, 469' left of centerline, up to 15' AGL/458' MSL. **Rwy 31**, tree 1.8 NM from departure end of runway, 1145' left of centerline, 15' AGL/514' MSL; tree 2.6 NM from departure end of runway, 3642' right of centerline, 15' AGL/599' MSL. **Rwys 13, 31**, ships up to 100' MSL located in water surrounding Sand Point.**SAVOONGA, AK****SAVOONGA**DEPARTURE PROCEDURE: **Rwy 23**, turn right, Aircraft departing via ULL R-260 CW R-080 climb on course. All others climb in holding pattern NE of ULL VOR right turn 226° inbound to cross ULL VOR at or above 3000.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



AK-1



TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

SCAMMON BAY, AK**SCAMMON BAY**

TAKE-OFF MINIMUMS: **Rwy 10**, 1500-2 or std. with a min. climb of 600' per NM to 1500.

DEPARTURE PROCEDURE: Departures limited to category A and B aircraft. **Rwy 10**, turn left as soon as practicable, climb heading 010° to 1000 before turning on course. **Rwy 28**, climb runway heading to 1600 before turning left.

SELAWIK, AK**SELAWIK**

NOTE: **Rwy 4**, multiple bushes beginning 176' from departure end of runway, 429' left of centerline, up to 18' AGL/18' MSL. **Rwy 22**, antenna on building, 1040' from departure end of runway, 448' right of centerline, 30' AGL/47' MSL. **Rwy 27**, multiple antennas and buildings beginning 270' from departure end of runway, right and left of centerline, up to 108' AGL/125' MSL. Bridge 2148' from departure end of runway, 249' right of centerline, 60' AGL/90' MSL.

SHUNGNAK, AK**SHUNGNAK**

DEPARTURE PROCEDURE: **Rwy 9**, climbing right turn direct AMF NDB. **Rwy 27**, climbing right turn direct AMF NDB.

SITKA, AK**SITKA ROCKY GUTIERREZ**

DEPARTURE PROCEDURE: Use BIORKA DEPARTURE.

SOLDOTNA, AK**SOLDOTNA**

TAKE-OFF MINIMUMS: **Rwy 25**, 200-1.

DEPARTURE PROCEDURE: **Rwy 7**, climb on a heading between 050° counter clockwise to 251° or 175° clockwise to 251° from departure end of runway. **Rwy 25**, climb heading 251° to 800, then climb on a heading between 160° clockwise to 065° from departure end of runway.

NOTE: **Rwy 7**, multiple trees beginning 1668' from departure end of runway, 454' right of centerline, up to 60' AGL/259' MSL. **Rwy 25**, multiple trees beginning 316' from departure end of runway, 517' left of centerline, up to 60' AGL/309' MSL.

SPARREVOHN LRRS, AK**SPARREVOHN**

TAKE-OFF MINIMUMS: **Rwy 16**, 500-1½ or std. with a min. climb of 420' per NM to 1900. Diverse departures not authorized.

DEPARTURE PROCEDURE: **Rwy 16**, use appropriate departure procedure. **Rwy 34**, NA.

TALKEETNA, AK**TALKEETNA**

TAKE-OFF MINIMUMS: **Rwys 18, 36**, 400-1.

DEPARTURE PROCEDURE: **Rwy 36**, turn left. **Rwy 18**, turn right. Climb southwestbound on TKA R-205 to 2000 then southbound V436 and southbound V491 turn left, continue climb on course. R-150 CW R-215, continue climb on course. All others reverse course, continue climb to TKA VOR/DME. Climb in holding pattern (S, left turns, 345° inbound) to depart TKA VOR/DME at or above: northbound V436, 3800; R-215 CWR-270, 6000; R-270 CWR-340, 19000; R-340 CWR-150, 5000.

TANANA, AK**RALPH M. CALHOUN MEMORIAL (TAL)****AMDT 1 07354 (FAA)**

TAKE-OFF MINIMUMS: **Rwy 7**, std. w/ a min. climb of 405' per NM to 1300, or 1200-2½ for climb in visual conditions. **Rwy 25**, std. w/ a min. climb of 230' per NM to 600, or 1200-2½ for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 7**, climbing right turn via heading 102° and TAL VOR/DME R-081 to SATUE/TAL 12 DME, or climb in visual conditions to cross Ralph M. Calhoun Memorial at or above 1300 then climb via TAL VOR/DME R-081 to SATUE. **Rwy 25**, climbing left turn via heading 078° and TAL VOR/DME R-081 to SATUE, or climb in visual conditions to cross Ralph M. Calhoun Memorial at or above 1300 then climb via TAL VOR/DME R-081 to SATUE. All aircraft continue climb in SATUE/12 DME holding pattern (hold east, left turn, 261° inbound) to cross SATUE at or above 4000 before proceeding on course.

NOTE: **Rwy 7**, multiple trees beginning 9000' from departure end of runway, 2149' left of centerline, up to 60' AGL/809' MSL. **Rwy 25**, trees 845' from departure end of runway, 1156' right of centerline, up to 60' AGL/459' MSL.

TIN CITY LRRS, AK**TIN CITY**

DEPARTURE PROCEDURE: **Rwy 16**, use appropriate departure procedure. **Rwy 34**, NA.
NOTE: Diverse departures NA.

TOGIAK VILLAGE, AK**TOGIAK**

TAKE-OFF MINIMUMS: **Rwys 10, 28**, NA-environmental
DEPARTURE PROCEDURE: **Rwy 3**, climb heading 028° to 1000, then climbing right turn to 2800 direct TOG NDB/DME, continue climb in TOG NDB/DME holding pattern (hold southwest, right turn, 023° inbound) to cross TOG NDB/DME at or above 2800 before proceeding on course. **Rwy 21**, climb heading 208° to 1000, then climbing left turn to 2800 direct TOG NDB/DME, continue climb in TOG NDB/DME holding pattern (hold southwest, right turn, 023° inbound) to cross TOG NDB/DME at or above 2800 before proceeding on course.

NOTE: **Rwy 21**, boats beginning 150' from departure end of runway, 500' left of centerline, up to 50' AGL/50' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008





TAKE-OFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES



07354

TOK, AK

TOK JUNCTION

TAKE-OFF MINIMUMS: **Rwy 7**, std. with a min. climb of 280' per NM to 2700, or 1200-3 for climb in visual conditions. **Rwy 25**, 300-1½ or std. with a min. climb of 360' per NM to 2300 and 230' per NM to 3600, or 1200-3 for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 7**, climb to 8000 via heading 070° and ORT VORTAC R-286 direct ORT VORTAC, or for climb in visual conditions: cross Tok Junction Airport at or above 2700, then continue climbing to 8000 via heading 070° and ORT VORTAC R-286 direct ORT VORTAC. **Rwy 25**, climb to 2300 via heading 251°, then climbing right turn to 8000 via heading 060° and ORT VORTAC R-286 direct ORT VORTAC, or for climb in visual conditions: cross Tok Junction Airport at or above 2700, then continue climbing to 8000 via heading 070° and ORT VORTAC R-286 direct ORT VORTAC.

NOTE: **Rwy 25**, tower 1 NM from departure end of runway, 2150' left of centerline, 228' AGL/1863' MSL.

TOKSOOK BAY, AK

TOKSOOK BAY

TAKE-OFF MINIMUMS: **Rwy 34**, std. with a min. climb of 495' per NM to 1800, or 1300-2½ for climb in visual conditions.

DEPARTURE PROCEDURE: **Rwy 16**, climb via heading 162° to 1000 before proceeding on course. **Rwy 34**, for climb in visual conditions: Cross Toksook Bay Airport at or above 1600.

NOTE: **Rwy 16**, multiple trees beginning 85' from departure end of runway, 300' right of centerline, up to 15' AGL/65' MSL. Multiple trees beginning 100' from departure end of runway, on centerline, up to 15' AGL/61' MSL.

UNALAKLEET, AK

UNALAKLEET

TAKE-OFF MINIMUMS: **Rwy 32**, 500-1. **Rwy 14**, turn right.

Rwy 8, immediate right turn. **Rwy 32**, immediate left turn. Northwest through southbound (280° CW 200°) climb on R-269 UNK VORTAC/270° bearing JNR NDB to cross VORTAC/NDB at or above 3000. Continue climb on course.

UNALASKA, AK

UNALASKA

TAKE-OFF MINIMUMS: **Rwy 12**, 1000-3. **Rwy 30**, 600-2.

DEPARTURE PROCEDURE: Maintain visual flight until intercepting the 355° bearing from DUT NDB/DME at 2 DME. Climb on the 355° bearing from DUT to 7000, then climb on course.

VALDEZ, AK

VALDEZ PIONEER FIELD

TAKE-OFF MINIMUMS: **Rwys 6, 24**, 3500-3.

Procedure NA at night.

DEPARTURE PROCEDURE: **Rwys 6, 24**, climb in visual conditions to MNL NDB (visual conditions must be maintained from takeoff until established over MNL NDB at or above 3500 MSL); cross MNL NDB at or above 3500 MSL, continue climb to 7000 via 233° bearing from MNL NDB, then climbing left turn to 10000 direct MNL NDB.

NOTE: **Rwy 6**, multiple bushes and trees beginning 2184' from departure end of runway, 662' left of centerline, up to 100' AGL/699' MSL. Multiple trees beginning 643' from departure end of runway, 470' right of centerline, up to 100' AGL/699' MSL. Obstruction light on LDA 6' from departure end of runway, 299' right of centerline, 79' AGL/148' MSL. Obstruction light on DME 22' from departure end of runway, 361' right of centerline, 79' AGL/148' MSL. Multiple trees beginning 623' from departure end of runway, 385' left of centerline, up to 100' AGL/130' MSL. Multiple trees beginning 469' from departure end of runway, 482' right of centerline, up to 100' AGL/139' MSL.

WALES, AK

WALES

TAKE-OFF MINIMUMS: **Rwy 18**, 400-1½ or std. with a min. climb of 445' per NM to 600.

DEPARTURE PROCEDURE: **Rwy 18**, climb via heading 177° until crossing TNC NDB/DME bearing 228° then turn left heading 018° to intercept the 048° course to TNC NDB/DME. **Rwy 36**, climb via heading 357° to 2000 then turn right heading 183° to intercept the 153° course to TNC NDB/DME.

NOTE: **Rwy 18**, trees 1.2 NM from departure end of runway, 2334' left of centerline, 50' AGL/349' MSL.

WASILLA, AK

WASILLA

TEXTUAL DEPARTURE: **Rwy 3**, turn left direct BGQ VORTAC: then, **Rwy 21**, turn right direct BGQ

VORTAC: then

Aircraft departing R-150 degrees clockwise through R-309, climb on course.

Aircraft departing R-310 degrees clockwise through R-149, climb in BGQ holding pattern to 4500 prior to departing on course. Hold N, RT, 168° inbound. Do not exceed 265 knots in holding.

WILLOW, AK

WILLOW

DEPARTURE PROCEDURE: Use BIG LAKE DEPARTURE.

WRANGELL, AK

WRANGELL

TAKE-OFF MINIMUMS: **Rwys 10, 28**, 1000-3.

DEPARTURE PROCEDURE: **Rwy 10**, turn left immediately. **Rwy 28**, climb on runway heading to 500. Proceed under VFR until established on LVD VOR R-059 or 059° bearing from SQM NDB. Climb to cross LVD VOR/SQM NDB at or above 4000.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008





07354

YAKUTAT, AK

YAKUTAT

DEPARTURE PROCEDURE: **Rwys 2, 11, 20, 29, All****aircraft** climb direct YAK VOR/DME or OCC NDB.

Thence...

... Aircraft continuing via radial/bearing 105 CW 280 proceed on course.

... All other aircraft climb in YAK VOR/DME holding pattern (SE, LT, 290° inbound) or OCC NDB holding pattern (W, RT, 112° inbound) to cross YAK VOR/DME or OCC NDB at or above 12,000 before proceeding on course.

NOTE: **Rwy 2**, multiple trees 458' from departure end of runway, 317' right of centerline, up to 76' AGL/99' MSL. Multiple trees 643' from departure end of runway, 342' left of centerline, up to 87' AGL/114' MSL. Tower 376' from departure end of runway, 243' left of centerline, 42' AGL/75' MSL. Obstruction light on glide slope 372' from departure end of runway, 238' left of centerline 34' AGL/67' MSL. Obstruction light on TMOM 593' from departure end of runway, 639' left of centerline, 24' AGL/51' MSL. **Rwy 11**, multiple trees beginning 95' from departure end of runway, 345' right of centerline, up to 75' AGL/98' MSL. Multiple trees beginning 121' from departure end of runway, from 377' left of centerline, up to 92' AGL/115' MSL. **Rwy 20**, multiple trees beginning 129' from departure end of runway, 297' right of centerline, up to 148' AGL/158' MSL. Multiple trees beginning 79' from departure end of runway, 283' left of centerline, up to 137' AGL/147' MSL. **Rwy 29**, multiple trees and bushes 122' from departure end of runway, 389' right of centerline, up to 123' AGL/153' MSL. Multiple trees and bushes 51' from departure end of runway, 65' left of centerline, up to 108' AGL/138' MSL.

13 MAR 2008 to 10 APR 2008

13 MAR 2008 to 10 APR 2008

