

ARRIVAL ROUTE DESCRIPTION

BESTT TRANSITION (BESTT.JONZE4)  
CNTLR TRANSITION (CNTLR.JONZE4)

LANDING RUNWAYS 18L/C/R: From JONZE on track 054° left turn to cross WHYLE between 10000 and 16000, then on track 054° to cross FREEK between 9000 and 11000 and at 250K, then on track 054° to DOSBE, then on track 003° to cross AAIRE at 9000 and at 210K, then on track 003° to cross JRDEN at 6000 and at 210K, then on track 003°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 36L/C/R: From JONZE on track 069° left turn to cross DUBBB between 10000 and 12000, then on track 080° to cross CHELE at 7000 and at 210K, then on track 090°. Expect RADAR vectors to final approach course.

SE-2, 18 APR 2024 to 16 MAY 2024

SE-2, 18 APR 2024 to 16 MAY 2024