

ILS or LOC/DME RWY 36
DANE COUNTY RGNL/TRUAX FLD (MSN)

MISSED APPROACH: Climb to 2700 on MSN VORTAC R-359 to DECAL INT/MSN 14.3 DME and hold.

MADISON
108.6 MSN [Chan 23]

LOCALIZER 110.1
I-MSN [Chan 38]

JANESVILLE
114.3 JVL [Chan 90]

ZIMIT
I-MSN [1.3]

PACOV
I-MSN [13.6]
JVL [23]

CUKRA
I-MSN [7.6]

RADAR
6000

OZMIX
I-MSN [4.6]

Procedure turn NA
for Cat E aircraft.

MISSED APCH FIX

ALTERNATE MISSED APCH FIX

ELEV 887 D TDZE 862

CATEGORY	A	B	C	D	E
S-ILS 36**	1062/24 200 (200-½)				
S-LOC 36	1240/24	378 (400-½)	1240/35 378 (400-¾)		
CIRCLING	1420-1	1460-1	1460-½	1700-2¾	1700-3
	533 (600-1)	573 (600-1)	573 (600-1½)	813 (900-¾)	813 (900-3)

DANE COUNTY RGNL/TRUAX FLD (MSN)
ILS or LOC/DME RWY 36

