

LOC I-BNE 110.7	APP CRS 337°	Rwy Idg TDZE Apt Elev	9003 161 168
---------------------------	------------------------	-----------------------------	---

ILS RWY 34 (CAT II & III)
RICHMOND INTL (RIC)

ATIS
119.15 263.025

POTOMAC APP CON
126.4 282.375 (001°-185°)
126.75 307.2 (186°-360°)

RICHMOND TOWER
121.1 257.8

GND CON
121.9 348.6

CLNC DEL
127.55 348.6

MISSED APCH FIX

ALTERNATE MISSED APCH FIX

LOCALIZER 110.7
I-BNE

RICHMOND
114.1 RIC Chan 88

HOPEWELL
114.35 HPW Chan 90 (Y)

MSA RIC 25 NM

ELEV 168 **D** **TDZE 161**

TDZ/CL Rwy 34
HIRL Rwy 2-20 and 16-34
REIL Rwy 20

800 **2000** **EPICS**

RIC R-018

JOMUS RIC 5.4 **JUVPO RIC 14.3**

1700 **1700** **1700**

337° **1700**

VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 79). **GS 3.00° TCH 54**

CATEGORY	A	B	C	D
S-ILS 34	CAT II RA 101/12 100 DA 261			
S-ILS 34	CAT III RVR 07			

CATEGORY II & III ILS-SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

NE-3, 18 APR 2024 to 16 MAY 2024

NE-3, 18 APR 2024 to 16 MAY 2024