

23334

RNAV (RNP) Z RWY 3R
PRESCOTT RGNL-ERNEST A LOVE FLD (PRC)

T For uncompensated Baro-VNAV systems, procedure NA below -11°C or above 54°C.

MISSED APPROACH: Climb to 9100 on track 028° direct PEVYU and hold.

Procedure NA for arrivals at MUMTE on V12 westbound.

(IAF) MUMTE

8800
115°
(26.8)

MSA RW03R 25 NM
9200

(IF) HOLEB

8100
028°
(6.9)

(FAI) GOVTE
7180
7180
7640
7163

5382
5101±
5210
5061
RW03R
5188±
6278±
5798
028°
(9.1)

028°
(18.6)

6962
7979
7000

Procedure NA for arrivals at KARLO on V105 southbound.

(IAF) KARLO

8800
310°
(11.7)

ELEV 5045 D TDZE 5022

MISSED APCH FIX
7 NM
028°
208°
PEVYU

MRL Rwy 12-30

REIL Rwy 3R, 12, and 30L

TWR 5087

184.6 X 60

76.9 X 130

440.9 X 75

0.8% UP

0.9% UP

028°

21R

21L

3R

30L

30R

AUTHORIZATION REQUIRED

PRESCOTT RGNL-ERNEST A LOVE FLD (PRC)
v RNAV (RNP) Z RWY 3R

34°39'N-112°25'W