

ILS or LOC/DME RWY 36
DANE COUNTY RGNL/TRUAX FLD (MSN)

MISSED APPROACH: Climb to 2700 on MSN VORTAC R-359 to DECAL INT/MSN 14.3 DME and hold.

2549 Δ

Δ 2365

(IAF)
OZMIX
I-MSN 4.6
RADAR
6000

CUKRA
I-MSN 7.6

(IF)
PACOV
I-MSN 13.6
JVL 23

2700 Δ 1159

Δ 1166

MADISON
108.6 MSN $\overline{\text{---}}$
Chan 23

Δ 1083

LOCALIZER 110.1
I-MSN $\overline{\text{---}}$
Chan 38

Δ 1354

Δ 1032

2700 to OZMIX
180° (6)

Δ 1112 $\pm$

ZIMIT
I-MSN 1.3

977

2500 Δ 1166

005° (3)

140°

350°

2700 Δ 1166

005° (6)

185°

3100 North
(23)

IAF
JANESVILLE
114.3 JVL $\overline{\text{---}}$
Chan 90

Procedure turn NA
for Cat E aircraft.

MISSED APCH FIX

117.0 DIL
R-115
Chan 117

359°

179°

108.6 MSN
R-359
Chan 23

DECAL INT
MSN 14.3

ALTERNATE MISSED
APCH FIX

270°

090° Δ 116.4 BAE
R-270
DREAR
Chan 111
BAE 33.7

MSA MSN 25 NM

180°

360°

3600

3100

ELEV 887 **D** TDZE 862

