


ILS or LOC RWY 22

MISSED APPROACH: Climb to 3000 on LGA VOR/DME R-225 to PROUD INT/LGA 11 DME and hold, continue climb-in-hold to 3000.



The diagram shows a perspective view of a runway. At the top, it indicates 'ELEV 21' and 'TDZE 12'. A heading of '224°' is shown with an arrow pointing towards the runway. The runway centerline is labeled '2200 X 150' and '7003 X 150'. Various lights are depicted along the runway edges and centerline, including threshold lights (A1, A5), side lights (H, S), and edge lights (P). A tower symbol is labeled 'TWR 240'. Below the diagram, there is a table titled 'FAF to MAP 5.7 NM' showing speeds in knots and times in minutes and seconds.

	Knots	60	90	120	150	180
Min:Sec	5:42	3:48	2:51	2:17	1:54	