

YAKIMA, WASHINGTON

AL-465 (FAA)

23334

VORTAC YKM 116.0 Chan 107	APP CRS 244°	Rwy Idg 7604 TDZE 1068 Apt Elev 1099
---	------------------------	---

VOR/DME or TACAN RWY 27
YAKIMA AIR TRML/MCALLISTER FLD (YKM)

T	Inoperative table does not apply.
A	Circling NA south of Rwy 9-27. When local altimeter setting not received, procedure NA.



MISSED APPROACH: Climb to 2600 via YKM VORTAC R-244, then climbing right turn to 4600 via YKM VORTAC R-276 to YKM VORTAC and hold, continue climb-in-hold to 4600 (TACAN aircraft, continue climb to 5000 via YKM VORTAC R-108 to SUNED/YKM 26 DME and hold west, right turns. 108° inbound).

ATIS 125.25	SPOKANE APP CON* 123.8 263.15	YAKIMA TOWER* 133.25 (CTAF) 0 257.8	GND CON 121.9	CLNC DEL 121.9	UNICOM 122.95
----------------	----------------------------------	--	------------------	-------------------	------------------