

LOC/DME I-FJD <u>110.55</u> Chan 42 (Y)	APP CRS 097°	Rwy Idg 6492 TDZE 23 Apt Elev 23
---	------------------------	---


ILS or LOC RWY 10R
TREASURE COAST INTL (FPR)

RNAV 1-GPS or DME required for procedure entry.


T
A Autopilot coupled approach NA below 720 MSL.

MISSED APPROACH: Climb to 1000 then climbing left turn to 2000 on heading 080° and TRV VORTAC R-132 to ANGEE INT/TRV 22.1 DME and hold.


ATIS 134.825	PALM BEACH APP CON 132.8	FORT PIERCE TOWER ★ 128.2 (CTAF) 0	GND CON (GCO) 119.55
------------------------	------------------------------------	--	--------------------------------




VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 52).



ELEV	23		TDZE	23
------	----	--	------	----



CATEGORY	A	B	C	D
S-ILS 10R	273- ³ / ₄		250 (300- ³ / ₄)	
S-LOC 10R	560-1	537 (600-1)	560-1 ¹ / ₂	537 (600-1 ¹ / ₂)
C CIRCLING	560-1	537 (600-1)	880-2 ¹ / ₂ 857 (900-2 ¹ / ₂)	880-2 ³ / ₄ 857 (900-2 ³ / ₄)
SIVYO FIX MINIMUMS (DME REQUIRED)				
S-LOC 10R	380-1		357 (400-1)	
C CIRCLING	460-1 437 (500-1)	480-1 457 (500-1)	880-2 ¹ / ₂ 857 (900-2 ¹ / ₂)	880-2 ³ / ₄ 857 (900-2 ³ / ₄)



REIL Rwys 10R and 28L **L**
MIRL all Rwys **L**

FORT PIERCE, FLORIDA
Amdt 4E 30JAN20

27°30'N-80°22'W

TREASURE COAST INTL (FPR)
ILS or LOC RWY 10R